



A LINCOLN ELECTRIC COMPANY

LightPro HD

FAILURE TO FOLLOW THESE INSTRUCTION CAN RESULT IN SERIOUS PERSONAL INJURY.

OPERATION STEPS



Attach burner onto butane / LPG cartridge



Turn on gas regulator



Press the knob to ignite




Regulate the flame using the hand wheel valve and torch is ready to be used!



A LINCOLN ELECTRIC COMPANY

LightPro HD



MATERIAL

No.	Component	Material
1	Gas Regulator	NL
2	Housing	BRASS
3	Burner tube	SS
4	Screw	FE
5	Bayonet connection	BRASS
6	O-ring	Rubber
7	Knob cover	NL



Remark:
The torch is NOT with anti-flare function.
Can't operate upside down.

size:W236xH178mm